

Inspection Photos

Location Name: BANTA RIDGE FED 10-19-1-103

Location ID: 05-103-10411

Inspection: 679702561



Photo 1. Location looking south.



Photo 2. Gas leaking along bottom threads of plunger.

