

*Inspection Photos
Donkey Well*



API#103-01020

Operator: Chevron

Inspection Number: 692400564

Inspection Date: 12/29/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:

Valve can, Historical equipment, July 21, 2017

July 21, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Chevron PA Donkey Well API#103-01020



Photo#2:
There is now No Evidence of the historical equipment.

July 21, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Chevron PA Donkey Well API#103-01020