

# *Inspection Photos*

*API#103-40008*

*Operator: Eagle Operating*

*Inspection Number: 692400567*

*Inspection Date: 12/28/2018*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
View of Location from Access road to Southeast.

December 28, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Eagle Op PA Emerald C 125 API#103-40008



Photo#2:  
Tanks located off of Northeast corner of Site.

December 28, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Eagle Op PA Emerald C 125 API#103-40008



Photo#3:  
View from tanks back to West.

December 28, 2018





Photo#4:  
Aerial image of site.

December 28, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Eagle Op PA Emerald C 125 API#103-40008