

Inspection Photos
Location Name:Rosenbrock#1
Location ID:319778



Photo#1 Production Tank and Produced Water Pit



Photo#2 Separator and Gas Meter

Inspection Photos
Location Name:Rosenbrock#1
Location ID:319778



Photo#3 Wellhead

