


**Inspection Photos**  
**Location Name:Collins 14-20**  
**Location ID:319747**



**Photo#1 Production Tank and Produced Water Pit**  
**Corrective Action Paint Tank**



**Photo#2 Separator/Gas Meter/Automation RTU**  
**Corrective Action Gas Meter needs Calibrated**

**Inspection Photos**  
**Location Name:Collins 14-20**  
**Location ID:319747**



**Photo#3 Wellhead**

