

Inspection Photos
Location Name:BoxElder 22-28
Location ID: 320454



Photo#1 Production Tank and Produced Water Pit



Photo#2 Separator/ECD

Inspection Photos
Location Name: Box Elder 22-28
Location ID: 320454



Photo#3 Wellhead



Photo#4 Corrective Action: Cover needs put back on pit