

Interim Reclamation and Stormwater Inspection

January 3, 2019

Operator: NOBLE ENERGY INC- #100322

Location ID: 445237

Inspection Document #: 682404392

Weld County, CO

SENW Section 24 T9N R59W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: LC24-6 /Tank
Location ID: 445237



Aerial imagery taken on January 3, 2019 illustrates the western Production Facility area does not appear to be needed for production operations. Operator shall comply with Rules 1002 and 1003.

Inspection Photos
Location Name: LC24-6 /Tank
Location ID: 445237



Photo 1. Photo taken from the northwestern location, facing East. Appears the Operator has ditch and berm BMP along the northern location which is directed to a stabilized outlet (sediment trap).

Inspection Photos
Location Name: LC24-6 /Tank
Location ID: 445237



Photo 2. Photo taken from the northwestern location, facing South. Photo illustrates unmanaged Kochia weeds along the western perimeter of the location.