

Photo#1:  
View North over Location.



Photo#2:  
View West over Well head.



August 31, 2017



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: D&D Resources TA Emerald 246 API#103-08888


Photo#3:

Tanks on Location



Photo#4:

Staining, leak from pipe at base of Tank.



August 31, 2017