

Inspection Photo (s)
CSF 41D
API # 05-045-23499
Inspection # 689302958



Location Photo #1



Location Photo #2

Inspection Photo (s)
CSF 41D
API # 05-045-23499
Inspection # 689302958



Location Photo #3



Location Photo #4, missing wildlife screen on tank burner in SE corner.

Inspection Photo (s)
CSF 41D
API # 05-045-23499
Inspection # 689302958



Location Photo #5, Missing labels on tank.



Location Photo #6, Missing labels on tank.

Inspection Photo (s)
CSF 41D
API # 05-045-23499
Inspection # 689302958



Location Photo #7, Missing labels on tank.



Location Photo #8, Bermed cuttings pile.