

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/15/2019

Submitted Date:

01/15/2019

Document Number:

691201069

FIELD INSPECTION FORM

Loc ID 332879 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

15 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
250273	WELL	PA	05/28/2014	GW	123-18076	ARIEL J 7-11	PA
270293	WELL	SI	01/01/2016	OW	123-21858	ARIEL J 7-14	SI

General Comment:

This is a WELL & BATTERY inspection.
4 - Other wells that were connected to this battery have been P&A'd.
Entire battery & equipment is shut-down.

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	TANK BATTERY		
Comment:	Chain link		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Chain link (Ariel J 7-14)		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Chain link		
Corrective Action:		Date:	
Equipment:			
Type: Ancillary equipment	# 2		corrective date
Comment:	ECD scrubbers		
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:	(Ariel J 7-14)		
Corrective Action:			Date:
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	200 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Shares berms w/ 300 Bbls. crude oil tank & produced H2O vault.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.416442,-104.830663
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment: Shares berms w/ 200 Bbls. crude oil tank & produced H2O vault.					
Corrective Action:				Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	CONCRETE SUMP/VAULT		,
Comment:					
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	53 Bbls.
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment: Shares berms w/ 200 Bbls. & 300 Bbls. crude oil tanks.					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 250273 Type: WELL API Number: 123-18076 Status: PA Insp. Status: PA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: _____

Corrective Action: Date: _____

Facility ID: 270293 Type: WELL API Number: 123-21858 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: _____

Corrective Action: Date: _____

BradenHead

Comment: _____

Corrective Action: Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Crew on site to begin dismantling and removal of all battery equipment.	evinsb	01/15/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691201070	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4705059