

Construction and Storm Water Inspection

January 15, 2019

Operator: NGL WATER SOLUTIONS DJ LLC - 10373

Location ID: 456888

Inspection Document #: 674902424

Weld County, CO

SWNE Section 30 T1N R66W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: NGL WATER SOLUTIONS DJ LLC – 10373/1N66W30

Location ID: 456888



Photo 1. Photo taken from the northeastern perimeter of the location, facing West. Photo illustrates a ditch and berm BMP that has been installed around the perimeter of the location.



Photo 2. Photo taken from the northeastern perimeter of the location, facing South. See comments from Photo 1.

Inspection Photos

Location Name: NGL WATER SOLUTIONS DJ LLC – 10373/1N66W30

Location ID: 456888



Photo 3. Photo taken from the northwestern perimeter of the location, facing South. See comments from Photo 1.



Photo 4. Photo taken from the northwestern perimeter of the location, facing East. See comments from Photo 1.

Inspection Photos

Location Name: NGL WATER SOLUTIONS DJ LLC – 10373/1N66W30

Location ID: 456888



Photo 5. Photo taken from the southwestern perimeter of the location, facing North. See comments from Photo 1.



Photo 6. Photo taken from the southwestern perimeter of the location, facing East. See comments from Photo 1.

Inspection Photos

Location Name: NGL WATER SOLUTIONS DJ LLC – 10373/1N66W30

Location ID: 456888



Photo 7. Photo taken from the southeastern perimeter of the location, facing North. See comments under Photo 1



Photo 8. Photo taken from the southeastern perimeter of the location, facing West. See comments under Photo 1. Also note no stabilized outlets observed on location.

Inspection Photos

Location Name: NGL WATER SOLUTIONS DJ LLC – 10373/1N66W30

Location ID: 456888



Photo 9. Photo taken from the northern perimeter of the location. The topsoil stockpile being stored along the western area has been temporarily stabilized with equipment tracking.



Photo 10. Photo taken from the northern perimeter of the location. See comments from Photo 9.

Inspection Photos

Location Name: NGL WATER SOLUTIONS DJ LLC – 10373/1N66W30

Location ID: 456888



Photo 11. Photo taken from the entrance of the location off CR 27, facing North. Appears Operator has not installed any tracking device or gravel to potentially limit tracking onto the county road.



Photo 12. Photo taken from the Western perimeter of the location, facing South. Photo depicts soil Filtrexx BMPs apparently ran over by equipment.