

Production Dump Line Pressure Test																	
Area = Piceance		County = Garfield		Test Year = 2017		Test Length = 15 min using separator gas pressure. 10% or greater loss is a failed test.											
ROUTE	PAD	Battery	Well	API	Tank A	Tank B	Tank C	Tank D	Tank E	Tank F	Date	Start Time	End Time	Start PSI	End PSI	Dump LineSize	Operator
ROUTE 9	K29NE	K29NE BAT-A	K29NE\ COUEY 29-12	045	10011	81264					5/23/2017	16:45	17:00	185	179	2"	derick m
ROUTE 9	K29NE	K29NE BAT-B	K29NE\ CRUZ 29-11A	045	11630	81896					5/23/2017	16:00	16:15	105	104	2"	derick m
ROUTE 9	K29NE	K29NE BAT-C	K29NE\ CRUZ 29-12A	045	11629	81895					5/23/2017	16:05	16:20	118	116	2"	derick m
ROUTE 9	K29NE	K29NE BAT-D	K29NE\ CRUZ 29-12C	045	11628	81897					5/23/2017	16:10	16:25	156	153	2"	derick m
ROUTE 9	K29NE	K29NE BAT-E/F	K29NE\ ROBINSON 29-10	045	10012	81263					6/14/2017	13:45	14:00	200	195	2"	art hutto
ROUTE 9	K29NE	K29NE BAT-E/F	K29NE\ ROBINSON 29-6	045	10195	81263					5/23/2017	16:35	16:50	160	158	2"	derick m
ROUTE 9	K29NE	K29NE BAT-G	K29NE\ SHIDELER 29-11	045	07953	81262					5/23/2017	16:40	16:55	170	170	2"	derick m