

Inspection Photos

Location Name: WEAVER RIDGE 13-9, 13-9H, 13-16

Location ID: 05-103-10580, 11781, 11782

Inspection: 679702652



Photo 1. Location looking north.



Photo 2. Location looking northeast.



Inspection Photos

Location Name: WEAVER RIDGE 13-9, 13-9H, 13-16

Location ID: 05-103-10580, 11781, 11782

Inspection: 679702652



Photo 3. Trash next to compressor.



Photo 4. All tanks missing 400 bbl capacity.



Inspection Photos

Location Name: WEAVER RIDGE 13-9, 13-9H, 13-16

Location ID: 05-103-10580, 11781, 11782

Inspection: 679702652



Photo 5. No wellhead sign on 13-9.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: WEAVER RIDGE 13-9, 13-9H, 13-16

Location ID: 05-103-10580, 11781, 11782

Inspection: 679702652



Photo 6. Container without label.



Photo 7. Container without label.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources