

**Inspection Photos**  
**Location Name: Hill Ranch #34-08**  
**Location ID: 308317**



**Photo 1 SEP**

**Photo 2 WH packing leaking**

**Inspection Photos**  
**Location Name: Hill Ranch #34-08**  
**Location ID: 308317**



**Photo 3 Unused equipment Pipe and polis rod**

**Photo 4 Unused equipment door from shed**

**Inspection Photos**  
**Location Name: Hill Ranch #34-08**  
**Location ID: 308317**



**Photo 5 Stained soil around motor skid**

**Photo 6 Stained soil around motor skid**