

**Inspection Photos**  
**Location Name: Hill Ranch #03-12V**  
**Location ID: 308037**



**Photo 1 Sep door is not attached considered trash**



**Photo 1 WH\Motor skid**