

Inspection Photos
Location Name: APACHE CANYON 02-14
Location ID: 308578



PHOTO 3: STAINED SOIL WEST SIDE OF COMPRESSOR SKID IN FRONT OF SCRUBBER



PHOTO 4: STAINED SOIL NORTH SIDE OF COMPRESSOR SKID UNDER DRAIN PLUG

Inspection Photos
Location Name: APACHE CANYON 02-14
Location ID: 308578



PHOTO 1: WELLHEAD



**PHOTO 2: SKID CONTAINMENT IS FULL OF FLUID AND
RUNNING OVER**