

Inspection Photos
Location Name: AC 09-07
Location ID: 307298



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN

Inspection Photos
Location Name: AC 09-07
Location ID: 307298



PHOTO 3: STAINED SOIL NORTH SIDE OF ENGINE SKID

PHOTO 4: CHECK VALVE BROKE LEAKING CLEAR FLUID

Inspection Photos
Location Name: AC 09-07
Location ID: 307298



PHOTO 5: UNMARKED UNUSED RISER/ NO PLUG

PHOTO 6: UNMARKED UNUSED RISER/ NO PLUG

Inspection Photos
Location Name: AC 09-07
Location ID: 307298



PHOTO 7: UNMARKED UNUSED RISER/ NO PLUG

