

Inspection Photos

Location Name:

Location ID:



Colorado Oil & Gas Conservation Commission
37.14627, -104.55296, 268°
2019/01/16 09:45:55

PHOTO 1: WELLHEAD



Colorado Oil & Gas Conservation Commission
37.07313, -104.85677, 2371.0m, 251°
2019/01/16 09:56:10

PHOTO 2: WELL SIGN/METER HOUSE

Inspection Photos
Location Name: HILL RANCH EAST 23-07
Location ID: 309367



**PHOTO 3: OILY APPEARING FLUID FLOATING ON WATER
PUDDLE UNDER DRIVEHEAD HYDRAULIC MOTOR**



PHOTO 4: FLUID LEAKING FROM ROD PACKING BOX