

Inspection Photos
Location Name: HILL RANCH 27-02V
Location ID: 307943



Colorado Oil & Gas Conservation Commission
37.06159, -104.87174, 2399.0m, 92°
2019/01/16 12:53:30

PHOTO 1: WELLHEAD



Colorado Oil & Gas Conservation Commission
37.06151, -104.87153, 2380.0m, 303°
2019/01/16 12:55:52

PHOTO 2: WELL SIGN/METER HOUSE

Inspection Photos
Location Name: HILL RANCH 27-02V
Location ID: 307943



PHOTO 3: TIMBER FENCE IN DISREPAIR



PHOTO 4: ROTTEN TIMBERS FROM FENCE PILED AROUND PIT