

Final Reclamation and Stormwater Inspection

January 15, 2019

Operator: PDC ENERGY INC - 69175

Location ID: 320330

Inspection Document #: 674902427

Adams County, CO

NWNW Section 21 T1S R68W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: PDC ENERGY INC - 69175/1S68W21

Location ID: 320330



Photo 1. Photo taken looking into the location, facing Southwest. Appears the Operator has performed reclamation activities with straw crimped mulch and drill rows.

Photo 2. Photo taken from the location, facing West. See comments from Photo 1.

Inspection Photos

Location Name: PDC ENERGY INC - 69175/1S68W21

Location ID: 320330



Photo 2. Photo taken from the location, facing Northwest. See comments from Photo 1.



Photo 3. Photo taken from the access road, facing West. See comments from Photo 1.

Inspection Photos

Location Name: PDC ENERGY INC - 69175/1S68W21

Location ID: 320330



Photo 5. Photo taken from the access road, facing East. See comments from Photo 1.



Photo 6. Photo taken from the access road, facing East. See comments from Photo 1.