

**Inspection Photos**  
**Location Name: CDP/Ellison 29-1**  
**Spill/Release Point ID #460502**



**210 bbl. AST where spill/release occurred.**



**210 bbl. AST on Ellison 33-5 #29-1 location.**

**Inspection Photos**  
**Location Name: CDP/Ellison 29-1**  
**Spill/Release Point ID #460502**



**Rust colored staining on AST and adjacent equipment.**



**210 bbl. AST and associated equipment are stained with rust colored residue.**