

Final Reclamation and Stormwater Inspection

December 20, 2018

Operator: KERR MCGEE OIL & GAS # 47120

Location ID: 317593

Inspection Document #: 674902434

Weld County, CO

SWSW Section 1 T1N R67W

Russell Beam
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: KERR MCGEE /1N67W1
Location ID: 317593



Photo 1. Photo taken from the well location looking towards the facility, facing East. Appears the Operator has performed final reclamation activities on the well location and the facility, with the evidence of drilling rows and straw crimped mulch.



Photo 2. Photo taken from the well location, facing East. See comments from Photo 1.

Inspection Photos
Location Name: KERR MCGEE /1N67W1
Location ID: 317593



Photo 3. Photo taken from the facility, facing South. See comments from Photo 1.



Photo 4. Photo taken from the facility, facing East. See comments from Photo 1.

Inspection Photos
Location Name: KERR MCGEE /1N67W21
Location ID: 317593



Photo 5. Photo taken from the facility. Note the length of the grass seed germination within the mulched area.



Photo 6. Photo taken from the facility. Note the shorter length of the grass seed germination within the areas where the mulch has dissipated.