

GV 80-4
Api # 05-045-06687
Inspection # 689702435



Well sign photo

GV 80-4
Api # 05-045-06687
Inspection # 689702435



01.17.2019 11:05

Battery sign.

GV 80-4
Api # 05-045-06687
Inspection # 689702435



Dead weeds around wells.

GV 80-4
Api # 05-045-06687
Inspection # 689702435



Dead weeds around wells.

GV 80-4
Api # 05-045-06687
Inspection # 689702435



Dead weeds around wells.

GV 80-4
Api # 05-045-06687
Inspection # 689702435



Dead weeds around separators.

GV 80-4
Api # 05-045-06687
Inspection # 689702435



Dead weeds between tank battery and separators.

GV 80-4
Api # 05-045-06687
Inspection # 689702435



Dead weeds around separators.

GV 80-4
Api # 05-045-06687
Inspection # 689702435



Dead weeds around tanks.