

Final Reclamation and Stormwater Inspection

December 20, 2018

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 319948

Inspection Document #: 674902438

Adams County, CO

SWNE Section 5 T1S R65W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: KERR MCGEE /1S65W5

Location ID: 319948



Photo 1. Photo taken from the location, facing West. Appears the Operator has performed final reclamation activities at the location and access road , with the evidence of drill rows.



Photo 2. Photo taken from the location, facing South. See comments from Photo 1.

Inspection Photos

Location Name: KERR MCGEE /1S65W5

Location ID: 319948



Photo 3. Photo taken from the location, facing South. See comments from Photo 1.



Photo 4. Photo taken from the access road looking into the location, facing West. See comments from Photo 1.