

Final Reclamation and Stormwater Inspection

December 20, 2018

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 336256

Inspection Document #: 674902441

Weld County, CO

SWSW Section 12 T1N R67W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: KERR MCGEE /1N67W12
Location ID: 336256



Photo 1. Photo taken from the location, facing Northeast. Appears the Operator has performed final reclamation activities at the location and access road, with the evidence of drill rows.



Photo 2. Photo taken from the location, facing South. See comments under Photo 1.