

Final Reclamation and Stormwater Inspection

January 15, 2019

Operator: NOBLE ENERGY PRODUCTION INC – 10120

Location ID: 409042

Inspection Document #: 674902440

Weld County, CO

SWSE Section 27 T3N R62W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: NOBLE ENERGY PRODUCTION INC/3N61W32

Location ID: 409042



Photo 1. Photo taken from the entrance to the access road looking towards the well location, facing West. Appears the Operator has performed final reclamation activities, with the evidence of drilling rows and straw crimped mulch and fenced the entire reclaimed area.



Photo 2. Photo taken from the access road, facing East. Although the reclaimed location is fenced, there was no gate across the entrance to the access road and cattle activity was observed throughout the reclaimed area.

Inspection Photos

Location Name: NOBLE ENERGY PRODUCTION INC/3N61W32

Location ID: 409042



Photo 3. Photo taken from the well location, facing North. See comments from Photo 1.



Photo 4. Photo taken from the well location, facing East. See comments from Photo 1.

Inspection Photos

Location Name: NOBLE ENERGY PRODUCTION INC/3N61W32

Location ID: 409042



Photo 5. Photo taken from the well location, facing South. See comments from Photo 1.



Photo 6. Photo taken from the well location, facing West. See comments from Photo 1.