

Inspection Photos  
Location Name: AC 17-13  
Location ID: 307376



Photo 1 SEP



Photo 1 WH and unused, unmaked risers not LOTO

**Inspection Photos**  
**Location Name: AC 17-13**  
**Location ID: 307376**



**Photo 3 Unused, unmarked riser not LOTO**

