

Inspection Photos
Location Name: AC 18-13
Location ID: 308937



Colorado Oil and Gas Conservation Commission
37.07786, -104.9338, 2444.9m
Jan 17, 2019 09:50:13

Photo 1 SEP



Colorado Oil and Gas Conservation Commission
37.07784, -104.9338, 2446.5m
Jan 17, 2019 09:50:34

Photo 2 Loc Pic

Inspection Photos
Location Name: AC 18-13
Location ID: 308937



Photo 3 Stained soil around WH



Photo 4 Stained soil around liquid ring compressor

Inspection Photos
Location Name: AC 18-13
Location ID: 308937



Photo 5 Stained soil around liquid ring compressor