

Inspection Photos
Location Name: AC 19-04VX
Location ID:308063



Photo 1 SEP and trash next to sep



Photo 2 Loc pic with stained soil next to Liquid Ring

Inspection Photos
Location Name: AC 19-04VX
Location ID:308063



Photo 3 Stained soil around liquid ring and WH



Photo 4 Stained soil around liquid ring

Inspection Photos
Location Name: AC 19-04VX
Location ID:308063



Photo 5 Stained soil around drain plug of liquid ring



Photo 6 Stained soil around drain plug of liquid ring

Inspection Photos
Location Name: AC 19-04VX
Location ID:308063



Photo 7 stained soil under 1" drain line from separator



Photo 6 soil sample taken by drain plug to liquid ring