

Location ID: 423142



Photo 1 Sep



Photo 2 WH/Motor skid

Inspection Photos
Location Name: AC 20-03
Location ID: 423142



Photo 3 VLV leaking at time of inspection




Photo 4 WH packing leaking at time of inspection

Inspection Photos
Location Name: AC 20-03
Location ID: 423142



Photo 5 Unused poly pipe on location