

Inspection Photos
Location Name: APACHE CANYON 12-03
Location ID: 308594



PHOTO 1: WELLHEAD



PHOTO 2: WELL SIGN/METER HOUSE

Inspection Photos
Location Name: APACHE CANYON 12-03
Location ID: 308594



PHOTO 3: TBG HEAD PACKING LEAKING FLUID ONTO LOCATION



PHOTO 4: STAINED SOIL OUTSIDE OF COMPRESSOR SKID THAT APPEARS TO BE COMING FROM SCRUBBER DRAIN

Inspection Photos
Location Name: APACHE CANYON 12-03
Location ID: 308594



PHOTO 5: ANOTHER PHOTO OF STAINED SOIL NEAR COMPRESSOR SCRUBBER DRAIN



PHOTO 6: STAINED SOIL NEAR EXHAUST PIPE OF COMPRESSOR SKID

Inspection Photos
Location Name: APACHE CANYON 12-03
Location ID: 308594



**PHOTO 7: EXISTING HOLE NEAR COMPRESSOR SKID DRAIN
PLUG APPEARS TO HAVE STAINED SOIL IN HOLE**



PHOTO 6: SAMPLE EXTRACTION POINT