

Inspection Photos


Loc#335851

Operator: Caerus

Inspection Number: 692400333

Inspection Date: 10/25/2018





Photo#1:
Overview of Location from Entry gate.

october 25,, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Parachute Abandoned Loc#335851



Photo#2:

Vegetation across location areas appears well established & diverse.

october 25,, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Parachute Abandoned Loc#335851



Photo#3:
Vegetation across location appears well established.

october 25,, 2018



Photo#4:


Photo#5:

october 25,, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Parachute Abandoned Loc#335851



Photo#6:
Weed growth will need to be monitored.

Photo#7:
Weed growth will need to be monitored.

october 25,, 2018