

Final Reclamation and Stormwater Inspection

January 18, 2019

Operator: KERR MCGEE OIL & GAS # 47120

Location ID: 428886

Inspection Document #: 674902455

Weld County, CO

NENE Section 2 T1N R67W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: KERR MCGEE /1N67W2
Location ID: 428886



Photo 1. Photo taken from the access road looking into the location, facing Northeast. Appears the Operator has removed all well equipment from the two P&A wells on the Active Location.



Photo 2. Photo taken from the well location, facing Southeast. See comments from Photo 1.