

Inspection Photo (s)
Clough NR 311-3
API # 05-045-23903
Inspection # 689303016



Location Photo #1

Location Photo #2

Inspection Photo (s)
Clough NR 311-3
API # 05-045-23903
Inspection # 689303016



Location Photo #3



Location Photo #4

Inspection Photo (s)
Clough NR 311-3
API # 05-045-23903
Inspection # 689303016



Location Photo #5, Condensate around base of tanks.

Location Photo #6, Condensate around base of tanks.

Inspection Photo (s)
Clough NR 311-3
API # 05-045-23903
Inspection # 689303016



Location Photo #7, Condensate around base of tanks.

Location Photo #8, Condensate around base of tanks.

Inspection Photo (s)
Clough NR 311-3
API # 05-045-23903
Inspection # 689303016



Location Photo #9, Condensate around base of tanks.

Location Photo #10, Condensate around base of tanks.