

**Inspection Photo (s)**  
**Valley Farms I-5**  
**API # 05-045-18166**  
**Inspection # 689303020**



**Location Photo #1**



**Location Photo #2**



**Inspection Photo (s)**  
**Valley Farms I-5**  
**API # 05-045-18166**  
**Inspection # 689303020**



**Location Photo #3, Stained ground by this unit.**



**Location Photo #4, Stained ground next separator.**



**Inspection Photo (s)**  
**Valley Farms I-5**  
**API # 05-045-18166**  
**Inspection # 689303020**



**Location Photo #5, Condensate on ground next to separator.**



**Location Photo #6, Condensate on ground next to separator.**

**Inspection Photo (s)**  
**Valley Farms I-5**  
**API # 05-045-18166**  
**Inspection # 689303020**



**Location Photo #7, Condensate on ground by separator.**