

Inspection Photo (s)
Valley Farms L 34C
API # 05-045-22446
Inspection # 689303024



Location Photo #1



Location Photo #2

Inspection Photo (s)
Valley Farms L 34C
API # 05-045-22446
Inspection # 689303024



Location Photo #3



Location Photo #4, Condensate in battery containment.

**Inspection Photo (s)
Valley Farms L 34C
API # 05-045-22446
Inspection # 689303024**



Location Photo #5, Condensate in battery containment.



Location Photo #6, Condensate in battery containment.

Inspection Photo (s)
Valley Farms L 34C
API # 05-045-22446
Inspection # 689303024



Location Photo #7, Mechanical condition of equipment.