

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/22/2019

Submitted Date:

01/22/2019

Document Number:

689303020

**FIELD INSPECTION FORM**

Loc ID 335553 Inspector Name: Holtz, Darin On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10447  
Name of Operator: URSA OPERATING COMPANY LLC  
Address: 1600 BROADWAY ST STE 2600  
City: DENVER State: CO Zip: 80202

**Findings:**

- 19 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
301518	WELL	PR	02/12/2009	GW	045-18166	VALLEY FARMS I5	PR
301519	WELL	XX	09/29/2017	LO	045-18167	Valley Farms I13	ND
301520	WELL	PR	06/21/2010	GW	045-18168	Valley Farms I10	PR
301521	WELL	XX	09/29/2017	LO	045-18169	Valley Farms I8	ND
301522	WELL	XX	09/29/2017	LO	045-18170	VALLEY FARMS I9	ND
417367	WELL	PR	03/02/2012	GW	045-19492	Valley Farms I3	PR
417372	WELL	PR	10/29/2012	GW	045-19493	Valley Farms I12	PR
417376	WELL	PR	10/29/2012	GW	045-19494	Valley Farms I6	PR
417378	WELL	PR	10/08/2013	GW	045-19495	Valley Farms I1	PR
417380	WELL	SI	02/01/2018	GW	045-19496	VALLEY FARMS I1H	TA
417383	WELL	PR	07/13/2012	GW	045-19497	Valley Farms I2	PR
417385	WELL	PR	10/29/2012	GW	045-19498	Valley Farms I11	PR
417656	WELL	PR	08/03/2014	GW	045-19590	Valley Farms I7	PR
435784	WELL	XX	09/29/2017	LO	045-22292	Valley Farms I15	ND
435785	WELL	XX	09/29/2017	LO	045-22293	Valley Farms I14	ND
435786	WELL	XX	09/29/2017	LO	045-22294	Valley Farms I16	ND
435787	WELL	XX	09/29/2017	LO	045-22295	Valley Farms I18	ND

**General Comment:**

[Routine Field Inspection.](#)

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Emergency Contact Number:			
Comment:	1-855-625-9922		
Corrective Action:		Date:	
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Stained ground near separator in 2 different spots, see photos.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with Rule 907.e..		Date: 01/25/2019
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Panel gates.		
Corrective Action:		Date:	
<b>Equipment:</b>			
Type: Deadman # & Marked	# 3		corrective date
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	Water transfer line.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	chemical unit at wellhead.		
Corrective Action:		Date:	
Type: Plunger Lift	# 9		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 12	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		,
Comment:	1 tank is heated. 4 tanks in centralized containment.				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

**Flaring:**

Type	
Comment:	

Corrective Action:

Date:

Inspected Facilities									
Facility ID:	301518	Type:	WELL	API Number:	045-18166	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	301519	Type:	WELL	API Number:	045-18167	Status:	XX	Insp. Status:	ND
Facility ID:	301520	Type:	WELL	API Number:	045-18168	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	301521	Type:	WELL	API Number:	045-18169	Status:	XX	Insp. Status:	ND
Facility ID:	301522	Type:	WELL	API Number:	045-18170	Status:	XX	Insp. Status:	ND
Facility ID:	417367	Type:	WELL	API Number:	045-19492	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	417372	Type:	WELL	API Number:	045-19493	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	417376	Type:	WELL	API Number:	045-19494	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	417378	Type:	WELL	API Number:	045-19495	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	417380	Type:	WELL	API Number:	045-19496	Status:	SI	Insp. Status:	TA

<b>Idle Well</b>			
Purpose: <input type="checkbox"/> Shut In		<input checked="" type="checkbox"/> Temporarily Abandoned	
Reminder: _____		_____	
Comment: MIT is Current, DOC# 1726747 .			
Corrective Action: _____		Date: _____	

Facility ID: 417383    Type: WELL    API Number: 045-19497    Status: PR    Insp. Status: PR

<b>Producing Well</b>			
Comment: Well Producing on plunger lift.			
Corrective Action: _____		Date: _____	

Facility ID: 417385    Type: WELL    API Number: 045-19498    Status: PR    Insp. Status: PR

<b>Producing Well</b>			
Comment: Well Producing on plunger lift.			
Corrective Action: _____		Date: _____	

Facility ID: 417656    Type: WELL    API Number: 045-19590    Status: PR    Insp. Status: PR

<b>Producing Well</b>			
Comment: Well Producing on plunger lift.			
Corrective Action: _____		Date: _____	

Facility ID: 435784    Type: WELL    API Number: 045-22292    Status: XX    Insp. Status: ND

Facility ID: 435785    Type: WELL    API Number: 045-22293    Status: XX    Insp. Status: ND

Facility ID: 435786    Type: WELL    API Number: 045-22294    Status: XX    Insp. Status: ND

Facility ID: 435787    Type: WELL    API Number: 045-22295    Status: XX    Insp. Status: ND

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						

Comment: [Location is snow covered.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689303021	Inspection photo 689303021	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4710795">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4710795</a>