

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/22/2019

Submitted Date:

01/22/2019

Document Number:

689303022**FIELD INSPECTION FORM**

Loc ID 416703	Inspector Name: Holtz, Darin	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> OGCC Operator Number: <u>10447</u> Name of Operator: <u>URSA OPERATING COMPANY LLC</u> Address: <u>1600 BROADWAY ST STE 2600</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				<b>Findings:</b> <u>13</u> Number of Comments <u>1</u> Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>				

<b>Contact Information:</b>			
Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	<a href="#">All Inspections</a>

<b>Inspected Facilities:</b>							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
416726	WELL	PR	06/16/2016	LO	045-19343	Valley Farms J2	PR
416730	WELL	PR	06/16/2016	LO	045-19344	Valley Farms J4	PR
416879	WELL	PR	06/16/2016	LO	045-19392	Valley Farms J1	PR
416880	WELL	PR	11/07/2014	LO	045-19393	Valley Farms J3	PR
435965	WELL	DG	01/18/2015	LO	045-22316	Valley Farms J9	DG
435966	WELL	DG	01/20/2015	LO	045-22317	Valley Farms J15	DG
435967	WELL	DG	01/14/2015	LO	045-22318	Valley Farms J5	DG
435968	WELL	DG	01/17/2015	LO	045-22319	Valley Farms J8	DG
435969	WELL	DG	01/16/2015	LO	045-22320	Valley Farms J7	DG
435970	WELL	DG	01/14/2015	LO	045-22321	Valley Farms J6	DG
435971	WELL	DG	01/19/2015	LO	045-22322	Valley Farms J10	DG
435972	WELL	DG	01/21/2015	LO	045-22323	Valley Farms J16	DG
435973	WELL	DG	01/24/2015	LO	045-22324	Valley Farms J14	DG
436141	WELL	DG	01/25/2015	LO	045-22340	Valley Farms J13	DG
436144	WELL	DG	01/27/2015	LO	045-22341	Valley Farms J11	DG
436149	WELL	DG	01/26/2015	LO	045-22342	Valley Farms J12	DG

<b>General Comment:</b> <u>Routine Field Inspection.</u>
---

Location				
<b>Lease Road:</b>				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	TANK LABELS/PLACARDS			
Comment:	Sign information inaccurate on 3 condensate tanks, see photo.			
Corrective Action:	Install sign to comply with Rule 210.d.			Date: 02/22/2019
Emergency Contact Number:				
Comment:	1-855-625-9922			
Corrective Action:				Date:
<b>Good Housekeeping:</b>				
Type	TRASH			
Comment:				
Corrective Action:				Date:
Type	DEBRIS			
Comment:				
Corrective Action:				Date:
Overall Good: <input checked="" type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	WELLHEAD			
Comment:	Panel gates.			
Corrective Action:				Date:
<b>Equipment:</b>				
Type: Bird Protectors	# 4			corrective date
Comment:				
Corrective Action:				Date:
Type: Plunger Lift	# 4			
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 4			

Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment: <a href="#">Water transfer lines.</a>			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment: <a href="#">Chemical unit at wellhead.</a>			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLs	STEEL AST		,
Comment: <a href="#">1 tank is heated.</a> <a href="#">6 tanks in a centralized containment.</a>					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					
Date:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					
Date:					

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

--	--	--

Inspected Facilities									
Facility ID:	416726	Type:	WELL	API Number:	045-19343	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	416730	Type:	WELL	API Number:	045-19344	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	416879	Type:	WELL	API Number:	045-19392	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	416880	Type:	WELL	API Number:	045-19393	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	435965	Type:	WELL	API Number:	045-22316	Status:	DG	Insp. Status:	DG
Facility ID:	435966	Type:	WELL	API Number:	045-22317	Status:	DG	Insp. Status:	DG
Facility ID:	435967	Type:	WELL	API Number:	045-22318	Status:	DG	Insp. Status:	DG
Facility ID:	435968	Type:	WELL	API Number:	045-22319	Status:	DG	Insp. Status:	DG
Facility ID:	435969	Type:	WELL	API Number:	045-22320	Status:	DG	Insp. Status:	DG
Facility ID:	435970	Type:	WELL	API Number:	045-22321	Status:	DG	Insp. Status:	DG
Facility ID:	435971	Type:	WELL	API Number:	045-22322	Status:	DG	Insp. Status:	DG
Facility ID:	435972	Type:	WELL	API Number:	045-22323	Status:	DG	Insp. Status:	DG
Facility ID:	435973	Type:	WELL	API Number:	045-22324	Status:	DG	Insp. Status:	DG

Facility ID: 436141	Type: WELL	API Number: 045-22340	Status: DG	Insp. Status: DG
Facility ID: 436144	Type: WELL	API Number: 045-22341	Status: DG	Insp. Status: DG
Facility ID: 436149	Type: WELL	API Number: 045-22342	Status: DG	Insp. Status: DG

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Retention Ponds						
Berms						

Comment: [Location is snow covered.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689303023	Inspection photo 689303023	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4710796">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4710796</a>