

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/22/2019

Submitted Date:

01/22/2019

Document Number:

689303024**FIELD INSPECTION FORM**

Loc ID 436713	Inspector Name: Holtz, Darin	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>10447</u> Name of Operator: <u>URSA OPERATING COMPANY LLC</u> Address: <u>1600 BROADWAY ST STE 2600</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				Findings: 19 Number of Comments 2 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	All Inspections

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
436712	WELL	XX	06/01/2016	LO	045-22360	Valley Farms L 43A-11-06-92	ND
436714	WELL	PR	06/08/2015	GW	045-22361	Valley Farms L 44D-11-06-92	PR
436715	WELL	PR	05/24/2015	GW	045-22362	Valley Farms L 44B-11-06-92	PR
436716	WELL	PR	03/20/2015	GW	045-22363	Valley Farms L 41B-14-06-92	PR
436718	WELL	XX	06/01/2016	LO	045-22364	Valley Farms L 44A-11-06-92	ND
436719	WELL	XX	06/01/2016	LO	045-22365	Valley Farms L 43C-11-06-92	ND
436720	WELL	XX	06/01/2016	LO	045-22366	Valley Farms L 43D-11-06-92	ND
436721	WELL	PR	03/19/2015	GW	045-22367	Valley Farms L 41A-14-06-92	PR
436722	WELL	PR	04/22/2015	GW	045-22368	Valley Farms L 44C-11-06-92	PR
436723	WELL	XX	06/01/2016	LO	045-22369	Valley Farms L 43B-11-06-92	ND
437661	WELL	XX	06/06/2016	LO	045-22434	VALLEY FARMS L 42D-11-06-92	ND
437662	WELL	DG	03/22/2018	LO	045-22435	VALLEY FARMS L 42C-11-06-92	ND
437663	WELL	XX	06/06/2016	LO	045-22436	VALLEY FARMS L 42B-11-06-92	ND
437714	WELL	XX	06/06/2016	LO	045-22438	VALLEY FARMS L 32C-11-06-92	ND

437715	WELL	PR	05/26/2015	GW	045-22439	VALLEY FARMS L 33D-11-06-92	PR
437718	WELL	XX	06/13/2016	LO	045-22440	VALLEY FARMS L 33C-11-06-92	ND
437729	WELL	PR	03/21/2015	GW	045-22443	VALLEY FARMS L 34D-11-06-92	PR
437730	WELL	XX	06/06/2016	LO	045-22444	VALLEY FARMS L 32D-11-06-92	ND
437742	WELL	XX	05/07/2014	LO	045-22445	VALLEY FARMS L 33A-11-06-92	ND
437753	WELL	PR	03/25/2015	GW	045-22446	VALLEY FARMS L 34C-11-06-92	PR
437760	WELL	XX	06/06/2016	LO	045-22447	VALLEY FARMS L 32B-11-06-92	ND
437771	WELL	XX	06/13/2016	LO	045-22448	VALLEY FARMS L 33B-11-06-92	ND
437776	WELL	PR	04/26/2015	GW	045-22449	VALLEY FARMS L 34A-11-06-92	PR
437782	WELL	PR	05/12/2015	LO	045-22450	VALLEY FARMS L 34B-11-06-92	PR
443129	WELL	XX	09/04/2015	LO	045-22976	VALLEY FARMS L 14B-12-06-92	ND
443130	WELL	XX	09/04/2015	LO	045-22977	VALLEY FARMS L 14C-12-06-92	ND

General Comment:[1-855-625-9922](tel:1-855-625-9922)

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good: ☒

Emergency Contact Number:

Comment: 1-855-625-9922

Corrective Action:

Date:

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:		Date:	
Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☐

Spills:			
Type	Area	Volume	
Condensate	Tank	<= 1 bbl	
Comment:	Condensate in tank containment, see photo.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a.		Date: 01/25/2019

In Containment: Yes

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel gates.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Flow Line	# 1		
Comment:	Water transfer line.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 6		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 10		
Comment:			
Corrective Action:		Date:	

Type: Bird Protectors	# 9	
Comment:		
Corrective Action:		Date:
Type: Emission Control Device	# 2	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 12	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 2	
Comment:	Chemical units at wellheads.	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLs	STEEL AST		,
Comment:	1 tank is heated. 6 tanks in a centralized containment. Dripping process controller on condensate tank, see photo.				
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.				Date: 02/22/2019

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					
Date:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					
Date:					

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Comment:					
Corrective Action:					Date: <div></div>
<u>Venting:</u>					
Yes/No	NO				
Comment:					
Corrective Action:					Date: <div></div>
<u>Flaring:</u>					
Type					
Comment:					
Corrective Action:					Date: <div></div>

Inspected Facilities				
Facility ID:	436712	Type:	WELL	API Number: 045-22360 Status: XX Insp. Status: ND
Facility ID:	436714	Type:	WELL	API Number: 045-22361 Status: PR Insp. Status: PR
<div>Producing Well</div> <div> <div>Comment: Well Producing on plunger lift.</div> <div> <div>Corrective Action:</div> <div>Date:</div> </div> </div>				
Facility ID:	436715	Type:	WELL	API Number: 045-22362 Status: PR Insp. Status: PR
<div>Producing Well</div> <div> <div>Comment: Well Producing on plunger lift.</div> <div> <div>Corrective Action:</div> <div>Date:</div> </div> </div>				
Facility ID:	436716	Type:	WELL	API Number: 045-22363 Status: PR Insp. Status: PR
<div>Producing Well</div> <div> <div>Comment: Well Producing on plunger lift.</div> <div> <div>Corrective Action:</div> <div>Date:</div> </div> </div>				
Facility ID:	436718	Type:	WELL	API Number: 045-22364 Status: XX Insp. Status: ND
Facility ID:	436719	Type:	WELL	API Number: 045-22365 Status: XX Insp. Status: ND
Facility ID:	436720	Type:	WELL	API Number: 045-22366 Status: XX Insp. Status: ND
Facility ID:	436721	Type:	WELL	API Number: 045-22367 Status: PR Insp. Status: PR
<div>Producing Well</div> <div> <div>Comment: Well Producing on plunger lift.</div> <div> <div>Corrective Action:</div> <div>Date:</div> </div> </div>				
Facility ID:	436722	Type:	WELL	API Number: 045-22368 Status: PR Insp. Status: PR
<div>Producing Well</div> <div> <div>Comment: Well Producing on plunger lift.</div> <div> <div>Corrective Action:</div> <div>Date:</div> </div> </div>				
Facility ID:	436723	Type:	WELL	API Number: 045-22369 Status: XX Insp. Status: ND
Facility ID:	437661	Type:	WELL	API Number: 045-22434 Status: XX Insp. Status: ND

Facility ID:	437662	Type:	WELL	API Number:	045-22435	Status:	DG	Insp. Status:	ND
Facility ID:	437663	Type:	WELL	API Number:	045-22436	Status:	XX	Insp. Status:	ND
Facility ID:	437714	Type:	WELL	API Number:	045-22438	Status:	XX	Insp. Status:	ND
Facility ID:	437715	Type:	WELL	API Number:	045-22439	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Well Producing on plunger lift.								
Corrective Action:							Date:		
Facility ID:	437718	Type:	WELL	API Number:	045-22440	Status:	XX	Insp. Status:	ND
Facility ID:	437729	Type:	WELL	API Number:	045-22443	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Well Producing on plunger lift.								
Corrective Action:							Date:		
Facility ID:	437730	Type:	WELL	API Number:	045-22444	Status:	XX	Insp. Status:	ND
Facility ID:	437742	Type:	WELL	API Number:	045-22445	Status:	XX	Insp. Status:	ND
Facility ID:	437753	Type:	WELL	API Number:	045-22446	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Well Producing on plunger lift.								
Corrective Action:							Date:		
Facility ID:	437760	Type:	WELL	API Number:	045-22447	Status:	XX	Insp. Status:	ND
Facility ID:	437771	Type:	WELL	API Number:	045-22448	Status:	XX	Insp. Status:	ND
Facility ID:	437776	Type:	WELL	API Number:	045-22449	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Well Producing on plunger lift.								
Corrective Action:							Date:		
Facility ID:	437782	Type:	WELL	API Number:	045-22450	Status:	PR	Insp. Status:	PR

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						

Comment: [Location is snow covered.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689303025	Inspection photo 689303025	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4710797