

Final Reclamation and Stormwater Inspection

January 21, 2019

Operator: KERR MCGEE OIL & GAS # 47120

Location ID: 336168

Inspection Document #: 674902454

Weld County, CO

NESE Section 8 T3N R67W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: KERR MCGEE /3N67W8
Location ID: 336168



Photo 1. Photo taken from the location, facing South. Appears the Operator has removed all well equipment from the two P&A wells on the Active Location.



Photo 2. Photo taken from the well location, facing Southwest. See comments from Photo 1.