

# Final Reclamation Inspection

January 16, 2019

Operator: SRC ENERGY INC- #10311

Location ID: 330116

Inspection Document #: 682404439

Weld County, CO

SENE Section 1 T5N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: ROTHE #1-14  
Location ID: 330116



**Photo 1.** Photo taken from the entrance of the location, facing West. Operator has performed final reclamation activities throughout the access road and well location, with the evidence of drilling rows and straw crimped mulch.



**Photo 2.** Photo taken from the southeastern location, facing North. See comments under Photo 1.



Inspection Photos  
Location Name: ROTHE #1-14  
Location ID: 330116



**Photo 3.** Photo taken from the central location, facing North. See comments under Photo 1.



**Photo 4.** Photo taken from the southwestern access road, facing North. See comments under Photo 1.