


**Inspection Photos**  
**Location Name: ARNOLD-66N65W /21NE5E**  
**Location #: 330232**



**Photo #1**

**Arnold E 21-9 (API # 05-123-18676) wellsite**  
**No sign posted w/ Emergency number**  
**Weeds have been cleared**  
**Shut-In**  
*from prev. FIR*



**Photo #2**

**Arnold E 21-9 wellsite**  
**Temporarily Abandoned | TA**  
**LOTO**  
**Sign now posted w/ Emergency number**



**Inspection Photos**  
**Location Name: ARNOLD-66N65W /21NESE**  
**Location #: 330232**



**Photo #3**  
**Arnold E 21-9 wellsite**  
**TA | LOTO**  
**No Orange TA/SI tag per agreement**



**Photo #4**  
**Arnold E 21-9, Bickling 21-02 Battery site**  
**Abandoned**  
**Unused Equipment – Fence posts, walkways**



**Inspection Photos**  
**Location Name: ARNOLD-66N65W /21NE5E**  
**Location #: 330232**



Colorado Oil & Gas Conservation Commission  
40.47179, -104.66133, 1426.0m, 54°  
2018/11/09 04:15:51 PM

**Photo #5**

**Arnold E 21-9, Bickling 21-02 Battery site**

**Shut-In**

*from prev. FIR*



Colorado Oil & Gas Conservation Commission  
40.47184, -104.66074, 1415.0m, 264°  
2019/01/23 10:43:32 AM

**Photo #6**

**Arnold E 21-9, Bickling 21-02 Battery site**

**Abandoned – Equipment removed**

**Unused Equipment – Gas meter run**