

Final Reclamation Inspection

January 16, 2019

Operator: SRC ENERGY INC- #10311

Location ID: 331017

Inspection Document #: 682404443

Weld County, CO

NWNE Section 1 T5N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: HERTZKE #1-12
Location ID: 331017



Photo 1. Photo taken from the entrance of the location off 95th Ave., facing West. COGCC Staff couldn't access the PA locations because of a locked gate. SRC representative will meet COGCC Staff upon request at a future date to inspect the PA locations. Note: This was a shared access road with another Operator and the other Operator will also receive a similar inspection.

Inspection Photos
Location Name: HERTZKE #1-12
Location ID: 331017



Photo 2. Photo taken from the entrance of the location off 95th Ave., facing West.
See comments under Photo 1.