

**Inspection Photos**  
**Location Name:** LESSOR J-65N66W /21NWNE  
**Location #:** 332639



**Photo #1**

**Lessor J 21-8 (05-123-25927) wellsite**  
**No Emergency contact number posted**



**Photo #2**

**Lessor J 21-17 (05-123-25928) wellsite**  
**Shut-In | SI**  
**No Emergency contact number posted**



## Inspection Photos

**Location Name:** LESSOR J-65N66W /21NWNE

**Location #:** 332639



Colorado Oil & Gas Conservation Commission  
40.39041, -104.78156, 1470.0m, 322°  
2019/01/23 02:37:22 PM

### Photo #3

**Lessor J 21-7X (05-123-25926) wellsite**

**Plugged & Abandoned | P&A**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

**Location Name:** LESSOR J-65N66W /21NWNE

**Location #:** 332639



### Photo #4

**Lesser PM J 21-1, 21-2, 21-8, 21-17,  
21-18D, 21-27D, 21-28D**

Battery



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources