

## Inspection Photos

Location Name: LESSER PM J-65N66W /21NWNE

Location #: 332717



**Photo #1**

**Lesser PM J 21-2 (05-123-14054) wellsite**

**No Emergency contact number posted**



**Photo #2**

**Lesser J 21-18D (05-123-29616) wellsite**

**No Emergency contact number posted**





## Inspection Photos

**Location Name:** LESSER PM J-65N66W /21NWNE

**Location #:** 332717



**Photo #3**

**Lesser J 21-27D (05-123-29615) wellsite**

**No Emergency contact number posted**



**Photo #4**

**Lesser J 21-28D (05-123-29613) wellsite**

**No Emergency contact number posted**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

**Location Name:** LESSER PM J-65N66W /21NWNE

**Location #:** 332717



### Photo #5

**Lesser PM J 21-1, 21-2, 21-8, 21-17,  
21-18D, 21-27D, 21-28D**

Battery



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources