

Inspection Photos

Location Name: DRAGON TRAIL UNIT 1072

Location ID: 05-103-09431

Inspection: 679702707



Photo 1. Location looking northeast.



Photo 2. Secondary containment liner for tank is torn .

