

Final Reclamation and Stormwater Inspection

January 16, 2019

Operator: SRC ENERGY INC- #10311

Location ID: 333286

Inspection Document #: 682404462

Weld County, CO

SWNE Section 4 T5N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SRC Northridge /21-4D
Location ID: 333286



Photo 1. Photo taken from the northeastern perimeter of location, facing South. Final reclamation is in-process. Surface roughening and silt fence BMP have been implemented along the toe of the disturbance area.

Inspection Photos
Location Name: SRC Northridge /21-4D
Location ID: 333286



Photo 2. Photo taken from the northeastern location, facing South. See comments under Photo 1.

Inspection Photos
Location Name: SRC Northridge /21-4D
Location ID: 333286



Photo 3. Photo taken from the northern location, facing South. See comments under Photo 1.