



**Inspected Facilities**

Facility ID: 216716 Type: WELL API Number: 069-05129 Status: PR Insp. Status: EI

**Environmental**

**Spill/Remediation:**

Comment: COGCC Environmental Staff onsite to observe soil sampling at historical spill location within the containment at Community tank battery. Sampling was conducted as proposed in approved Remediation Project #12232. Field observation did not indicate the presence of hydrocarbon impacted material at either sampling location. Operator will submit collected samples for laboratory analysis described in the approved Form 27. Operator will submit laboratory analytical results using eForm 27 Supplemental Report.

Corrective Action:  Date:

Emission Control Burner (ECB):

Comment:

Pilot:  Wildlife Protection Devices (fired vessels):

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693700134	Soil Sample Location Community Battery	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4713894">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4713894</a>