

Inspection Photos

Location Name: A.J. GOLD-65N66W /22SWSW

Location #: 329332



Colorado Oil & Gas Conservation Commission
40.37995, -104.77338, 1438.0m, 354°
2019/01/24 03:22:23 PM

Photo #1

A.J. Gold 22-13 (05-123-17189) wellsite

Shut-In | SI



Colorado Oil & Gas Conservation Commission
40.37956, -104.7726, 1453.0m, 327°
2019/01/24 03:30:39 PM

Photo #2

A.J. Gold 22-13 Battery

Shut-down



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources