

Inspection Photos
Location Name: TUSCANY /10-22-24
Location #: 332567



Photo #1
Strong 4-22 (05-123-11858) wellsite



Photo #2
Strong 4-22 Wellsite
Well sign

Inspection Photos

Location Name: TUSCANY /10-22-24

Location #: 332567



Photo #3

Strong 4-22 Battery



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: TUSCANY /10-22-24
Location #: 332567



Photo #4
Strong 4-22 Oil Tank
Stained soil under Loadout
from prev. FIR



Photo #5
Strong 4-22 Oil Tank
Stained soil under Loadout
Appears mitigated

Inspection Photos
Location Name: TUSCANY /10-22-24
Location #: 332567



Photo #6
Strong 4-22 Separator
Leaking fittings
from prev. FIR



Photo #7
Strong 4-22 Oil Tank
Leaking fittings
Appears mitigated
Stains are dry. No soil stains